
Flushing Meadows-Corona Park, Willow Lake

Queens · New York · Site ID 48 · Seasonal geometric mean of each season's regular samples (May–early October)




Good: ≤ 35 · Advisory: 35–104 · Poor: > 104 · Fewer than 5 samples that season

SWIM Coalition
Stormwater Infrastructure Matters

Flushing Meadows-Corona Park, Willow Lake: every sample

Queens · New York · Site ID 48 · DEC class B · 13 samples · overall geomean 291 · 69% over 104



SWIM Coalition
Stormwater Infrastructure Matters