Flushing Meadows-Corona Park, Meadow Lake

Queens · New York · Site ID 57 · Seasonal geometric mean of each season's regular samples (May–early October)




Good: ≤ 35 · Advisory: 35–104 · Poor: > 104 · Fewer than 5 samples that season

SWIM Coalition · Community Water Quality Testing · Data through Oct 1, 2026

SWIM Coalition
Stormwater Infrastructure Matters

Flushing Meadows-Corona Park, Meadow Lake: every sample

Queens · New York · Site ID 57 · DEC class B · 199 samples · overall geomean 452 · 70% over 104



SWIM Coalition
Stormwater Infrastructure Matters