Calvert Vaux Park, Coney Island Creek

Brooklyn · New York · Site ID 65 · Seasonal geometric mean of each season's regular samples (May–early October)




Good: ≤ 35 · Advisory: 35–104 · Poor: > 104 · Fewer than 5 samples that season

SWIM Coalition
Stormwater Infrastructure Matters

Calvert Vaux Park, Coney Island Creek: every sample

Brooklyn · New York · Site ID 65 · DEC class I · 52 samples · overall geomean 207 · 62% over 104



SWIM Coalition
Stormwater Infrastructure Matters