
Soundview Park (mouth), Bronx River

Bronx · New York · Site ID 85 · Seasonal geometric mean of each season's regular samples (May–early October)




Good: ≤ 35 · Advisory: 35–104 · Poor: > 104 · Fewer than 5 samples that season

SWIM Coalition
Stormwater Infrastructure Matters

Soundview Park (mouth), Bronx River: every sample

Bronx · New York · Site ID 85 · DEC class I · 56 samples · overall geomean 185 · 61% over 104



SWIM Coalition
Stormwater Infrastructure Matters