
Lincoln Avenue 2, Harlem River

Bronx · New York · Site ID 129 · Seasonal geometric mean of each season's regular samples (May–early October)




Good: ≤ 35 · Advisory: 35–104 · Poor: > 104 · Fewer than 5 samples that season

SWIM Coalition
Stormwater Infrastructure Matters

Lincoln Avenue 2, Harlem River: every sample

Bronx · New York · Site ID 129 · DEC class I · 57 samples · overall geomean 50 · 33% over 104



SWIM Coalition
Stormwater Infrastructure Matters